

Northen crack(red line) runs across the lake and is about 1m wide. Southern crack runs to the middle of the lake and turns north, from there runs north about 1km, Crack is about 10-30cm wide.

Ice overall is hard and dry. At point 26 ice has no cracks but is a bit bumpier than in the north. Suitable race areas marked with red circles.

Point 1. Thickness 32cm
Point 3. thickness 35cm
Point 4. thickness 74cm (ridged ice layered ontop of each other)
Point 6. thickness 37cm
Point 13. thickness 23cm
Point 18. thickness 28cm
Point 22. thickness 26cm



Pic 1. Ice thickness at point 1



Pic 2. Ice overview at point 1



Pic 3. Ice thickness at point 3



Pic 4. Ice overview at point 3.



Pic 5. Ice thickness at point 4.



Pic 6. Ridged ice at point 4 (about 50mx50m)



Pic 7. ice thickness at point 6



Pic 8. ice overview at point 6.



Pic 9. Ice thickness at point 13.



Pic 10. Ridgec ice at point 13.



Pic 11. Ice thickness at point 18



Pic 12. Ice overview at point 18



Pic 13. Ice thickness at pint 22



Pic 14. Jetty at Limnoliigia jaam (crack ends in about 100m)



Pic 15. jetty at limnoloogia jaam



pic 16. ice overview at Limnoloogia jaam